



STEAMBOAT OFFICE 24 B 5TH STREET STEAMBOAT SPRINGS, CO 80487



Issue Dates:

09/08/2023

11/16/2023

DEVELOPMENT PLAN

SUBMITTAL

DEVELOPMENT PLAN 2ND

STEAMBO

SITE PLAN LEGEND:

CENTERLINE BUILDING ROOF LINE/OVERHANG DECK ____ x ____ x ____ x ____ x ____ FENCE _____ 6800 _____ MAJOR CONTOUR MINOR CONTOUR ASPHALT CONCRETE GRAVEL SIGN DITCH/SWALE CULVERT W/ END SECTIONS

STORM MANHOLE, MANHOLE INLET,


NOTES:

1. THE MEASURED DISTANCES SHOWN HEREON ARE IN U.S. SURVEY FEET.

GRATE INLET AND CURB INLET

- 2. UNDERGROUND IMPROVEMENTS: LOCATIONS FOR UNDERGROUND IMPROVEMENTS ARE SHOWN HEREON PER ONE OR MORE OF THE FOLLOWING; VISIBLE AND APPARENT SURFACE EVIDENCE, AS-BUILT DRAWINGS PROVIDED BY OTHERS, MARKINGS PROVIDED BY COLORADO 811 ONE CALL SERVICES, PRIVATE UNDERGROUND LOCATING SERVICES, OR GIS INFORMATION. ANY METHOD OF SHOWING UNDERGROUND IMPROVEMENTS, OR ANY COMBINATION THEREOF, MAY NOT PROVIDE COMPLETE AND ACCURATE LOCATIONS FOR ALL UNDERGROUND IMPROVEMENTS. IF ACCURATE LOCATIONS FOR UNDERGROUND IMPROVEMENTS ARE REQUIRED, THEY WILL HAVE TO BE VERIFIED BY FIELD POTHOLING OF THE IMPROVEMENTS. LANDMARK CONSULTANTS, INC. AND THE SURVEYOR OR ENGINEER OF RECORD SHALL NOT BE LIABLE FOR THE FAILURE TO ACCURATELY AND COMPLETELY DEPICT THE LOCATIONS OF UNDERGROUND IMPROVEMENTS.
- ALL REFERENCES HEREON TO BOOKS, PAGES, FILES, PARCEL ID NUMBERS AND RECEPTION NUMBERS ARE TO PUBLIC DOCUMENTS FILED IN THE RECORDS OF ROUTT COUNTY, COLORADO.
- 4. PROJECT BENCHMARK: A RECOVERED REBAR W/ ORANGE PLASTIC CAP AS SHOWN HEREON, HAVING AN ELEVATION OF 6727.32' BASED ON THE NORTH AMERICAN VERTICAL DATUM OF 1988 (NAVD88) AS SHOWN HEREON.
- 5. CONTOUR INTERVAL = 1 FOOT
- SNOW REMOVAL IS THE RESPONSIBILITY OF THE DOWNTOWN RIVERVIEW METRO DISTRICT AND WILL BE HAULED OFFSITE AS REQUIRED.

Sheet Title CIVIL SITE PLAN





STEAMBOAT OFFICE 24 B 5TH STREET STEAMBOAT SPRINGS, CO 80487



Issue Dates:

DEVELOPMENT PLAN

SUBMITTAL

DEVELOPMENT PLAN 2ND

STEAMBO

SITE PLAN LEGEND:

ITET EXITEESEINE.		
CENTERLINE		
BUILDING	<u> </u>	
ROOF LINE/OVERHANG		
DECK		
WALL	L /./ \ \ \ /. / \ \ \ \ \ \ \ \ \ \ \ \ \	
FENCE	x x x x	
MAJOR CONTOUR		
MINOR CONTOUR		
ASPHALT		Jeeus Da
CONCRETE		Issue Da
GRAVEL		DATE
SIGN		DATE
DITCH/SWALE	· ·	09/08/2023
CULVERT W/ END SECTIONS		11/16/2023

NOTES:

1. THE MEASURED DISTANCES SHOWN HEREON ARE IN U.S. SURVEY FEET.

STORM MANHOLE, MANHOLE INLET, GRATE INLET AND CURB INLET

- 2. UNDERGROUND IMPROVEMENTS: LOCATIONS FOR UNDERGROUND IMPROVEMENTS ARE SHOWN HEREON PER ONE OR MORE OF THE FOLLOWING; VISIBLE AND APPARENT SURFACE EVIDENCE, AS-BUILT DRAWINGS PROVIDED BY OTHERS, MARKINGS PROVIDED BY COLORADO 811 ONE CALL SERVICES, PRIVATE UNDERGROUND LOCATING SERVICES, OR GIS INFORMATION. ANY METHOD OF SHOWING UNDERGROUND IMPROVEMENTS, OR ANY COMBINATION THEREOF, MAY NOT PROVIDE COMPLETE AND ACCURATE LOCATIONS FOR ALL UNDERGROUND IMPROVEMENTS. IF ACCURATE LOCATIONS FOR UNDERGROUND IMPROVEMENTS ARE REQUIRED, THEY WILL HAVE TO BE VERIFIED BY FIELD POTHOLING OF THE IMPROVEMENTS. LANDMARK CONSULTANTS, INC. AND THE SURVEYOR OR ENGINEER OF RECORD SHALL NOT BE LIABLE FOR THE FAILURE TO ACCURATELY AND COMPLETELY DEPICT THE LOCATIONS OF UNDERGROUND IMPROVEMENTS.
- 3. ALL REFERENCES HEREON TO BOOKS, PAGES, FILES, PARCEL ID NUMBERS AND RECEPTION NUMBERS ARE TO PUBLIC DOCUMENTS FILED IN THE RECORDS OF ROUTT COUNTY, COLORADO.
- 4. PROJECT BENCHMARK: A RECOVERED REBAR W/ ORANGE PLASTIC CAP AS SHOWN HEREON, HAVING AN ELEVATION OF 6727.32' BASED ON THE NORTH AMERICAN VERTICAL DATUM OF 1988 (NAVD88) AS SHOWN HEREON.
- 5. CONTOUR INTERVAL = 1 FOOT
- 6. SNOW REMOVAL IS THE RESPONSIBILITY OF THE DOWNTOWN RIVERVIEW METRO DISTRICT AND WILL BE HAULED OFFSITE AS REQUIRED.

Sheet Title

CIVIL SITE PLAN WITH AERIAL **IMAGE**

Sheet No. **C.101**