


# EXISTING CONDITIONS LEGEND:



## NO

- 1. THIS MAP DOES NOT REPRESENT A MONUMENTED LAND SURVEY. IT IS INTENDED ONLY TO DEPICT THAT INFORMATION REQUESTED BY OUR CLIENT.
- LAND TITLE GUARANTEE COMPANY TITLE COMMITMENT ORDER NO. ABC30031079, COMMITMENT DATE: 07/21/2023 WAS RELIED UPON TO DETERMINE OWNERSHIP AND EASEMENTS OF RECORD SHOWN ON THIS EXISTING CONDITIONS MAP UNLESS NOTED OTHERWISE. EASEMENTS NOTED "FROM PREVIOUS" ARE SHOWN BASED ON PREVIOUS SURVEYING PERFORMED IN THE AREA BY LANDMARK CONSULTANTS, INC. NO REPRESENTATION IS MADE BY LANDMARK CONSULTANTS, INC. OR THE SURVEYOR OF RECORD THAT ALL EASEMENTS SHOWN HEREON ARE STILL EXTANT, OR THAT ALL EASEMENTS OF RECORD WITHIN THE MAPPING AREA ARE SHOWN OR NOTED HEREON.
- BASIS OF HORIZONTAL CONTROL: THE 2011 ITERATION OF THE COLORADO COORDINATE SYSTEM OF 1983 NORTH ZONE, NAD83(2011) COLORADO NORTH, SCALED TO GROUND ABOUT A POINT HAVING COORDINATES OF 1412535.68, 2636559.05 AND A SCALE FACTOR OF 1,003600183
- UNITS SHOWN HEREON ARE IN US SURVEY FEET AND THE STANDARD OF DISTANCE ACCURACY FOR THIS MAP HAS BEEN DETERMINED TO BE GREATER THAN 1:10,000.

FLOOD ZONE INFORMATION IS SHOWN HEREON PER LETTER OF MAP REVISION 13-08-0214P,

EFFECTIVE JULY 8, 2013, AND LETTER OF MAP REVISION LOMR 18-08-0922P, EFFECTIVE JULY

- SITE BENCHMARK: A SET #5 REBAR WITH ORANGE PLASTIC CAP HAVING AN ELEVATION OF 6963.78 BASED ON THE NORTH AMERICAN VERTICAL DATUM OF 1988 (NAVD88) AS SHOWN HEREON.
- CONTOUR INTERVAL = 1 FEET


(SCALED TO APPROXIMATE DRIPLINE)

- 8. UNDERGROUND IMPROVEMENTS: LOCATIONS FOR UNDERGROUND IMPROVEMENTS ARE SHOWN HEREON PER ONE OR MORE OF THE FOLLOWING; VISIBLE AND APPARENT SURFACE EVIDENCE, AS-BUILT DRAWINGS PROVIDED BY OTHERS, MARKINGS PROVIDED BY COLORADO 811 ONE CALL SERVICES, PRIVATE UNDERGROUND LOCATING SERVICES, OR GIS INFORMATION. ANY METHOD OF SHOWING UNDERGROUND IMPROVEMENTS, OR ANY COMBINATION THEREOF, MAY NOT PROVIDE COMPLETE AND ACCURATE LOCATIONS FOR ALL UNDERGROUND IMPROVEMENTS. IF ACCURATE LOCATIONS FOR UNDERGROUND IMPROVEMENTS ARE REQUIRED, THEY WILL HAVE TO BE VERIFIED BY FIELD POTHOLING OF THE IMPROVEMENTS. LANDMARK CONSULTANTS, INC. AND THE SURVEYOR OR ENGINEER OF RECORD SHALL NOT BE LIABLE FOR THE FAILURE TO ACCURATELY AND COMPLETELY DEPICT THE LOCATIONS OF UNDERGROUND IMPROVEMENTS.
- 9. ALL REFERENCES HEREON TO BOOKS, PAGES, FILES AND RECEPTION NUMBERS ARE TO
- PUBLIC DOCUMENTS FILED IN THE RECORDS OF ROUTT COUNTY, COLORADO.
- 10. THE LAST FIELD INSPECTION OF THE SITE WAS ON 8/17/2023.
- 11. DRAWING PLOTS TO SCALE ON 24"x36" PAPER.
- 12. WATER AND SEWER INFORMATION SUPPLEMENTED USING MOUNT WERNER WATER RECORD INFORMATION. SOME DISCREPANCIES MAY EXIST.
- 13. ORDINARY HIGH WATER MARK IS SHOWN HEREON PER MARKINGS PROVIDED BY WESTERN

PROPERTY DESCRIPTION: THAT PARCEL OF LAND DESCRIBED IN RECEPTION NO. 816590 IN THE ROUTT COUNTY RECORDS; COUNTY OF ROUTT, STATE OF COLORADO.

DETAILED EXISTING CONDITIONS EXHIBITIONS EXHIBITIONS

C.003



#### **EXISTING CONDITIONS LEGEND:**

PROPERTY BOUNDARY	
ADJACENT PROPERTY BOUNDARY	
EASEMENT	
PROPERTY MONUMENT AS NOTED	•
[TC15] = REFERENCE TO TITLE COMMITMENT. SEE NOTE 2 EASEMENT SHOWN BASED ON PREVIOUS SURVEY	[TC15] <u>FROM PREVIOUS</u>
INFORMATION (SEE NOTE 2)	
LIMITS OF FLOOD ZONE AE (SEE NOTE 5)	L
BUILDING WALL	
FENCE	
MAJOR CONTOUR	
MINOR CONTOUR	
ASPHALT	
CONCRETE CURR W/ PAN	
CONCRETE CURB W/ PAN	· · · · · · · · · · · · · · · · · · ·
BRICK PAVERS	
GRAVEL	
ROCK/ BOULDERS/ RIP RAP	
SIGN	S N
SANITARY SEWER LINE MARKER MANHOLE AND CLEANOUT	₩xs_@_xsxs_@_xs_
SEPTIC TANK LID AND VENT PIPE	(S)
WATER LINE MAKER, FIRE HYDRANT GATE VALVE, CURB STOP & METER	₩ 
FIRE DEPT. CONNECTION, YARD HYDRANT, VENT PIPE, WATER MANHOLE AND WELL	<b>☆</b> ⊗ ℙ ∞
GAS LINE MARKER, VALVE, MANHOLE/VAULT, METER AND SHUTOFF	G VG—XG—XG—XG—XG—XG—XG—XG—
CABLE LINE MARKER, VAULT AND PEDESTAL	C XTV XTV XTV XTV XTV XTV
FIRED ORTIC LINE MARKED VALUET & DEDECTAL	FO
FIBER OPTIC LINE MARKER, VAULT & PEDESTAL  TELEPHONE LINE MARKER, VAULT, PEDESTAL AND MANHOLE	T
ELECTRIC LINE MARKER, TRANSFORMER, METER AND SECONDARY PEDESTAL	E
ELECTRIC MANHOLE, OUTLET, GENERATOR AND JUNCTION BOX	(E) REPORTED TO THE REPORT OF
LIGHT POLE, STREET LIGHT, TRAFFIC SIGNAL TRAFFIC CONTROL VAULT AND CABINET	☆
OVERHEAD UTILITY LINE GUY POLE, UTILITY POLE & GUY WIRE	Ф_хон—хон⊂хон—хон
EDGE OF WATER	
ORDINARY HIGH WATER MARK (SEE NOTE 13) DITCH/SWALE	
STORM SEWER SCALED TO PIPE DIMENSION LOCATION FOR INFORMATION ONLY	
STORM MANHOLE, MANHOLE INLET, GRATE INLET AND CURB INLET	(S)
STUMP, BOULDER AND IRRIGATION VALVE BOX	
CONIFEROUS AND DECIDUOUS TREE (SCALED TO APPROXIMATE DRIPLINE)	
CONIFEROUS AND DECIDUOUS SHRUB	

## NOT


- 1. THIS MAP DOES NOT REPRESENT A MONUMENTED LAND SURVEY. IT IS INTENDED ONLY TO DEPICT THAT INFORMATION REQUESTED BY OUR CLIENT.
- 2. LAND TITLE GUARANTEE COMPANY TITLE COMMITMENT ORDER NO. ABC30031079, COMMITMENT DATE: 07/21/2023 WAS RELIED UPON TO DETERMINE OWNERSHIP AND EASEMENTS OF RECORD SHOWN ON THIS EXISTING CONDITIONS MAP UNLESS NOTED OTHERWISE. EASEMENTS NOTED "FROM PREVIOUS" ARE SHOWN BASED ON PREVIOUS SURVEYING PERFORMED IN THE AREA BY LANDMARK CONSULTANTS, INC. NO REPRESENTATION IS MADE BY LANDMARK CONSULTANTS, INC. OR THE SURVEYOR OF RECORD THAT ALL EASEMENTS SHOWN HEREON ARE STILL EXTANT, OR THAT ALL EASEMENTS OF RECORD WITHIN THE MAPPING AREA ARE SHOWN OR NOTED HEREON.
- BASIS OF HORIZONTAL CONTROL: THE 2011 ITERATION OF THE COLORADO COORDINATE SYSTEM OF 1983 NORTH ZONE, NAD83(2011) COLORADO NORTH, SCALED TO GROUND ABOUT A POINT HAVING COORDINATES OF 1412535.68 ,2636559.05 AND A SCALE FACTOR OF 1 0003690183
- UNITS SHOWN HEREON ARE IN US SURVEY FEET AND THE STANDARD OF DISTANCE ACCURACY FOR THIS MAP HAS BEEN DETERMINED TO BE GREATER THAN 1:10,000.
- FLOOD ZONE INFORMATION IS SHOWN HEREON PER LETTER OF MAP REVISION 13-08-0214P, EFFECTIVE JULY 8, 2013, AND LETTER OF MAP REVISION LOMR 18-08-0922P, EFFECTIVE JULY 29, 2019.
- SITE BENCHMARK: A SET #5 REBAR WITH ORANGE PLASTIC CAP HAVING AN ELEVATION OF 6963.78 BASED ON THE NORTH AMERICAN VERTICAL DATUM OF 1988 (NAVD88) AS SHOWN HEREON.
- CONTOUR INTERVAL = 1 FEET
- UNDERGROUND IMPROVEMENTS: LOCATIONS FOR UNDERGROUND IMPROVEMENTS ARE SHOWN HEREON PER ONE OR MORE OF THE FOLLOWING; VISIBLE AND APPARENT SURFACE EVIDENCE, AS-BUILT DRAWINGS PROVIDED BY OTHERS, MARKINGS PROVIDED BY COLORADO 811 ONE CALL SERVICES, PRIVATE UNDERGROUND LOCATING SERVICES, OR GIS INFORMATION. ANY METHOD OF SHOWING UNDERGROUND IMPROVEMENTS, OR ANY COMBINATION THEREOF, MAY NOT PROVIDE COMPLETE AND ACCURATE LOCATIONS FOR ALL UNDERGROUND IMPROVEMENTS. IF ACCURATE LOCATIONS FOR UNDERGROUND IMPROVEMENTS ARE REQUIRED, THEY WILL HAVE TO BE VERIFIED BY FIELD POTHOLING OF THE IMPROVEMENTS. LANDMARK CONSULTANTS, INC. AND THE SURVEYOR OR ENGINEER OF RECORD SHALL NOT BE LIABLE FOR THE FAILURE TO ACCURATELY AND COMPLETELY DEPICT THE LOCATIONS OF UNDERGROUND IMPROVEMENTS.
- ALL REFERENCES HEREON TO BOOKS, PAGES, FILES AND RECEPTION NUMBERS ARE TO PUBLIC DOCUMENTS FILED IN THE RECORDS OF ROUTT COUNTY, COLORADO.
- PUBLIC DOCUMENTS FILED IN THE RECORDS OF ROUTT COU
- 10. THE LAST FIELD INSPECTION OF THE SITE WAS ON 8/17/2023.
- DRAWING PLOTS TO SCALE ON 24"x36" PAPER.
   WATER AND SEWER INFORMATION SUPPLEMENTED USING MOUNT WERNER WATER
- RECORD INFORMATION. SOME DISCREPANCIES MAY EXIST.

  13. ORDINARY HIGH WATER MARK IS SHOWN HEREON PER MARKINGS PROVIDED BY WESTERN

PROPERTY DESCRIPTION: THAT PARCEL OF LAND DESCRIBED IN RECEPTION NO. 816590 IN THE ROUTT COUNTY RECORDS; COUNTY OF ROUTT, STATE OF COLORADO.

SCONDITIONS AND SLOPE EXHIBIT
PARCEL OF LAND
SW1/4 SECTION 22,
RTH, RANGE 84 WEST OF THE 6TH P.M.;
MBOAT SPRINGS, COUNTY OF ROUTT,
STATE OF COLORADO

C.004



### EXISTING CONDITIONS LEGEND:

PROPERTY BOUNDARY ADJACENT PROPERTY BOUNDARY \_\_\_ \_ \_ \_ \_ \_ \_ \_ \_ \_ \_ PROPERTY MONUMENT SECTION CORNER HIGHWATER MARK FEMA FLOODWAY EDGE OF WATER WATER BODY SETBACK ROOF LINE/OVERHANG \_\_\_\_ x \_\_\_\_ x \_\_\_\_ x \_\_\_\_ x \_\_\_\_ \_\_\_\_\_ MAJOR CONTOUR MINOR CONTOUR SANITARY SEWER LINE MARKER ₩\_\_\_xs**\_**@\_xs\_\_\_xs**\_**@\_xs\_\_\_\_ MANHOLE AND CLEANOUT SEPTIC TANK LID AND VENT PIPE WATER LINE MAKER, FIRE HYDRANT XW—XXX—XX—XX—XXX—XXX GATE VALVE, CURB STOP & METER FIRE DEPT. CONNECTION, YARD HYDRANT, 
 ★
 Ø
 P
 Ø
 Ø
 VENT PIPE, WATER MANHOLE AND WELL GAS LINE MARKER, VALVE, MANHOLE/VAULT, METER AND SHUTOFF PROPANE TANK (BURIED) TTV—XTV—M—XTV—XTV—XTV—XTV CABLE LINE MARKER, VAULT AND PEDESTAL SATELLITE DISH XFO — FIBER OPTIC LINE MARKER, VAULT & PEDESTAL TELEPHONE LINE MARKER, VAULT, PEDESTAL AND MANHOLE ELECTRIC LINE MARKER, TRANSFORMER, XE-XE-XE-XE-XEM-XE-XEM METER AND SECONDARY PEDESTAL ELECTRIC MANHOLE, OUTLET, GENERATOR AND JUNCTION BOX LIGHT POLE, STREET LIGHT, TRAFFIC SIGNAL TRAFFIC CONTROL VAULT AND CABINET OVERHEAD UTILITY LINE Фхон—хон хон—хон— GUY POLE, UTILITY POLE & GUY WIRE EDGE OF WATER CULVERT W/ END SECTIONS STORM MANHOLE, MANHOLE INLET, GRATE INLET AND CURB INLET AIR CONDITIONER, MAILBOX, NEWSTAND, CONIFEROUS AND DECIDUOUS TREE (SCALED TO APPROXIMATE DRIPLINE) CONIFEROUS AND DECIDUOUS SHRUB (SCALED TO APPROXIMATE DRIPLINE)

\*ANTICIPATED EXISTING CONDITIONS EXHIBIT REFLECTS THE FUTURE EXISTING CONDITIONS AS A RESULT OF THE ONGOING SKI TIME SQUARE DRIVE TURNAROUND & COMPLETE STREET IMPROVEMENTS (BY OTHERS). FINAL CONDITIONS MAY DIFFER AND ARE SUBJECT TO CHANGE.

CALL UTILITY NOTIFICATION CENTER OF COLORADO

Know what's below.

Call before you dig.

CALL 2 BUSINESS DAYS IN ADVANCE BEFORE YOU DIG, GRADE, OR EXCAVATE FOR THE MARKING OF UNDERGROUND MEMBER UTILITIES.

SHEET C.010

service provided by Landmark
Consultants, Inc. and are not to be

used for any type of construction or

sealed by a Professional Engineer

in the employ of Landmark Consultants, Inc.

NOT FOR CONSTRUCTION