



INSPECTION REPORT

Report Issued: May 15, 2024

Inspection Result: **FAILED**

Permit Number: SPRSW210257

Issuance Date:

Property Address: 2305 MT WERNER CIR;

Applicant: Saunders Construction, LLC

Contractor: Rebecca Lindeman <NO STREET ADDRESS> CO

To construct: Gondola Relocation Project

On this day we have inspected your construction for **90 Day Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: project complete waiting on final stabilization.

Corrections:

- 1 The practice of cleaning out accumulated sediment from check dams along the Right of Way trail while runoff is occurring is causing sediment to discharge from the base area drainage to Burgess Creek. This practice needs to be re-evaluated and only occur when runoff is not occurring in the ditch. Please respond with a narrative outlining how this will be addressed in the future.

Sincerely,

Scott Slamal
Stormwater Inspector
sslamal@steamboatsprings.net

P.O. Box 775088, Steamboat Springs, Colorado 80477-5088
970.879.2060 ☎ 970.879.8851 (fax) ☎ steamboatsprings.net