



# INSPECTION REPORT

**Report Issued:** Aug 25, 2025

**Inspection Result:** **FAILED**

**Permit Number:** SPRSW250987

**Issuance Date:** Jul 03, 2025

**Property Address:** 34120 FOREST ROAD 321;

**Applicant:** NATIVE EXCAVATION

**Contractor:**

**To construct:** Sewer line replacement along Right-O-Way trail at Steamboat Resort

On this day we have inspected your construction for **45 Day Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Please make corrections by end of day Tuesday 8/26.

**Corrections:**

- 1 The FODs tracking pad needs to be re-staked per FODs specifications.
- 2 Additional rock socks or wattle check dams are needed in the swale at the project entrance.

Sincerely,

Scott Slamal  
Stormwater Inspector  
sslamal@steamboatsprings.net

P.O. Box 775088, Steamboat Springs, Colorado 80477-5088  
970.879.2060 ☎ 970.879.8851 (fax) ☎ steamboatsprings.net