



INSPECTION REPORT

Report Issued: Oct 09, 2025

Inspection Result: **FAILED**

Permit Number: SPRSW250987

Issuance Date: Jul 03, 2025

Property Address: 34120 FOREST ROAD 321;

Applicant: NATIVE EXCAVATION

Contractor: Rebecca Lindeman <NO STREET ADDRESS> CO

To construct: Sewer line replacement along Right-Of-Way trail at Steamboat Resort

On this day we have inspected your construction for **45 Day Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Address corrections by October 11, 2025 and email photos once completed.

Corrections:

- 1 Reinstall rock socks where damaged at the bottom inlet noted during the inspection.
- 2 Maintain rock sock check dams in the swale at bottom edge of disturbance.
- 3 Consider installing wattles perpendicular to the slopes in various locations to slow runoff down and minimize erosion.

Sincerely,

Scott Slamal
Stormwater Inspector
sslamal@steamboatsprings.net

P.O. Box 775088, Steamboat Springs, Colorado 80477-5088
970.879.2060 ❄ 970.879.8851 (fax) ❄ steamboatsprings.net