



# INSPECTION REPORT

**Report Issued:** May 03, 2022

**Inspection Result:** **FAILED**

**Permit Number:** SPRSW210257

**Issuance Date:**

**Property Address:** 2305 MT WERNER CIR;

**Applicant:** Saunders Construction, LLC

**Contractor:**

**To construct:** Gondola Relocation Project

On this day we have inspected your construction for **45 Day Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Corrections must be completed immediately. Send photos once completed.

**Corrections:**

- 2 Install additional Dandy Bag inlet protection at the two inlets adjacent to the new gondola terminal.
- 3 Control measure implementation was inadequate to control sediment discharges to Burgess Creek.

Sincerely,

Scott Slamal  
Stormwater Inspector  
sslamal@steamboatsprings.net

P.O. Box 775088, Steamboat Springs, Colorado 80477-5088  
970.879.2060 ✪ 970.879.8851 (fax) ✪ steamboatsprings.net