



INSPECTION REPORT

Report Issued: Aug 19, 2022

Inspection Result: **FAILED**

Permit Number: SPRSW220558

Issuance Date: Jun 01, 2022

Property Address: 2400 MT WERNER CIR;

Applicant: Duckels Construction Inc.

Contractor:

To construct: New electrical conduit yvea duct bank project

On this day we have inspected your construction for **45 Day Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Please complete corrections by EOB 8/22 and email photos of corrections

Corrections:

- 1 Additional perimeter controls needed at toe of slope at corner of mt Werner and burgess creek rd at cutt slope down from the Grand, and below inlet along Mt Werner circle.
- 2 Install more adequate sediment barriers at problematic inlet down towards sidewalk on Mt Werner circle.
- 3 Sweep up sedimentation at bottom of bike path at Cornice rd.

Sincerely,

Scott Slamal
Stormwater Inspector
sslamal@steamboatsprings.net

P.O. Box 775088, Steamboat Springs, Colorado 80477-5088
970.879.2060 ✪ 970.879.8851 (fax) ✪ steamboatsprings.net