

20/2018 10:48:29 AM

EXTENT OF CORRIDOR AREA TO BE REPAIRED LEGEND

----- EXTENT* OF GYP. BD. ON CORRIDOR FACE OF WALL TO BE REPLACED (FINSIH TO MATCH ORIGINAL CONDITION - COORD. WITH OWNER) - REMOVE EXISTING INSULATION & REPLACE WITH R-21 FIBERGLASS BATT INSULATION - RE: DETAIL 6 / A101

 EXTENT* OF CEILING & FLOORING TO BE REPLACED:
GYP. BD. ON CEILING TO BE REPLACED (FINSIH TO MATCH ORIGINAL CONDITION - COORD. WITH OWNER) REMOVE EXISTING INSULATION & REPLACE WITH R-21 FIBERGLASS BATT INSULATION
EXISTING FLOORING TO BE REMOVED DOWN TO THE CONCRETE ASSEMBLY AND REPLACED TO MATCH ADJACENT FLOORING

* THE EXACT EXTENT OF WALL, FLOOR & CEILING TO BE REPLACED SHALL BE DETERMINED IN THE FIELD BASED ON THE EXTENT OF DAMAGE TO THE CORRIDOR ON A FLOOR BY FLOOR BASIS

