

EXTENT OF CORRIDOR AREA TO BE REPAIRED LEGEND

---- EXTENT\* OF GYP. BD. ON CORRIDOR FACE OF WALL TO BE REPLACED (FINSIH TO MATCH ORIGINAL CONDITION - COORD WITH OWNER) - REMOVE EXISTING INSULATION & REPLACE WITH R-21 FIBERGLASS BATT INSULATION - RE: DETAIL 6 / A101

EXTENT\* OF CEILING & FLOORING TO BE REPLACED: • GYP. BD. ON CEILING TO BE REPLACED (FINSI-GYP. BD. ON CEILING TO BE REPLACED (FINSIH TO MATCH ORIGINAL CONDITION - COORD. WITH OWNER) REMOVE EXISTING INSULATION & REPLACE WITH R-21 FIBERGLASS BATT INSULATION EXISTING FLOORING TO BE REMOVED DOWN TO THE CONCRETE ASSEMBLY AND REPLACED TO MATCH ADJACENT FLOORING

\* THE EXACT EXTENT OF WALL, FLOOR & CEILING TO BE REPLACED SHALL BE DETERMINED IN THE FIELD BASED ON THE EXTENT OF DAMAGE TO THE CORRIDOR ON A FLOOR BY FLOOR BASIS

## RCRBD **Record Set**

PJ3207-1 Fire Prevention In: 08/27/2018 Out: 08/27/2018

