

**NORTHWEST COLORADO CONSULTANTS, INC.  
FIELD REPORT**

**Project:** Torian Plum  
Window Header  
**Location:** SBS, CO  
**Client:** Torian Plum

**Project No.:** 23-13034

**Report No.:** 1-Fire

**Date:** 6/15/23  
**Time:** 6.0  
**Mileage:** 36  
**Engr. /Tech:** CR

**Work Performed:**

As requested, we visited the project site over a period of two days to provide special inspections and measurements of the intumescent paint product applied to the four window header columns.

**Remarks:**

Based on our visual observations and recorded thickness of the intumescent fireproofing the product measurements meet or exceed the data that was provided to us.

It should be noted that today's observations are made with respect to the paint thickness only and do not constitute a complete special inspection of the structure. Elements such as layout, size, elevation or other architectural aspects are not considered in our observations.

**Verbal Discussions:**

Pat Farrell of Garcia Construction was notified of today's observations.