



INSPECTION REPORT

Report Issued: May 15, 2024

Inspection Result: **FAILED**

Permit Number: SPRSW210256

Issuance Date:

Property Address:

Applicant: NATIVE EXCAVATION

Contractor: Saunders Construction, LLC 86 Inverness Place North Englewood, CO 80112
Rebecca Lindeman, Jardon Engineering PO Steamboat Springs, CO 80477
(303) 517-8189

To construct: Excavation work for Green Horn Ranch - Ski area

On this day we have inspected your construction for **90 Day Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments:

Corrections:

- 1 Additional rocks needed in sediment basin to prevent spilling and provide additional capacity to promote settling.

Sincerely,

Scott Slamal
Stormwater Inspector
sslamal@steamboatsprings.net

P.O. Box 775088, Steamboat Springs, Colorado 80477-5088
970.879.2060 ✪ 970.879.8851 (fax) ✪ steamboatsprings.net