



INSPECTION REPORT

Report Issued:	Dec 27, 2024	nspection Result	t: NOT READY
Permit Number:	SPRNR231281		
Issuance Date:	Jan 22, 2024		
Property Address:	3300 S LINCOLN AVE;		
Applicant:	Maurer Construction LLC		
Contractor:	Maurer Construction LLC 262	1 Connery Way Mis	ssoula, MT 59808 (406) 542-
	6565		
To construct:	New construction of a 63,527 GSF 4-story, 90 unit hotel		

On this day we have inspected your construction for **Framing Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Moved to a Drywall inspection

Corrections:

Sincerely,

Jeff Yeiser Inspector jyeiser@co.routt.co.us