



INSPECTION REPORT

Report Issued:	Feb 04, 2025	Inspection Resu	ult:	PARTIAL PAS	55
-					
Permit Number:	SPRNR231281				
Issuance Date:	Jan 22, 2024				
Property Address:	3300 S LINCOLN AVE;				
Applicant:	Maurer Construction LLC				
Contractor:	Maurer Construction LLC 26	21 Connery Way N	Aissou	ıla, MT 59808 (40	06) 542-
	6565				
To construct:	New construction of a 63,52	7 GSF 4-story, 90 u	nit ho	tel	

On this day we have inspected your construction for **Drywall Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: 3rd floor, drywall and fire caulk above ceiling in bath too corridor, all units complete

Corrections:

Sincerely,

Jeff Yeiser Inspector jyeiser@co.routt.co.us