



## **INSPECTION REPORT**

Report Issued:	Feb 06, 2025	Inspection Result:	<b>FAILED</b>
----------------	--------------	--------------------	---------------

Permit Number: SPRNR231281
Issuance Date: Jan 22, 2024

**Property Address:** 3300 S LINCOLN AVE;

**Applicant:** Maurer Construction LLC

Contractor: Maurer Construction LLC 2621 Connery Way Missoula, MT 59808 (406) 542-

6565

**To construct:** New construction of a 63,527 GSF 4-story, 90 unit hotel

On this day we have inspected your construction for **Framing Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** 2nd floor fire caulking not complete

**Corrections:** 

Sincerely,

Jeff Yeiser Inspector jyeiser@co.routt.co.us