



INSPECTION REPORT

Report Issued: Feb 20, 2025 Inspection Result: PARTIAL PASS

Permit Number: SPRNR231281 Issuance Date: Jan 22, 2024

Property Address: 3300 S LINCOLN AVE;

Applicant: Maurer Construction LLC

Contractor: Maurer Construction LLC 2621 Connery Way Missoula, MT 59808 (406) 542-

6565

To construct: New construction of a 63,527 GSF 4-story, 90 unit hotel

On this day we have inspected your construction for **Drywall Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: 1st floor corridors, top horseshoe double layer installed. 2nd floor RC channel installed in all units. 3rd floor drywall complete in all units. All 5/8" type x

Corrections:

Sincerely,

Jeff Yeiser Inspector jyeiser@co.routt.co.us