



# INSPECTION REPORT

**Report Issued:** Apr 01, 2025

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** SPRNR231281

**Issuance Date:** Jan 22, 2024

**Property Address:** 3300 S LINCOLN AVE;

**Applicant:** Maurer Construction LLC

**Contractor:** Maurer Construction LLC 2621 Connery Way Missoula, MT 59808 (406) 542-6565

**To construct:** New construction of a 63,527 GSF 4-story, 90 unit hotel

On this day we have inspected your construction for **Insulation Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Sound insulation has been installed on the main floor in all interior walls, there are some areas where insulation will be added yet, the insulation is installed properly and you may continue to add it as you drywall other rooms, no more sound insulation inspections required on the main floor.

**Corrections:**

Sincerely,

Todd Carr  
Building Official  
tcarr@co.routt.co.us