



INSPECTION REPORT

Report Issued:	Sep 23, 2021	Inspection Result:	PARTIAL PASS
Permit Number: Issuance Date: Property Address:	B-21-204 Apr 14, 2021 2305 MT WERNER CIR;		
Contractor:	Saunders Construction, LL (408) 656-9910	C 86 Inverness Place North	Englewood, CO 80112
To construct:	Work Description: Relocat mountain. Lift and Operate Colorado Tram Board. Pro- for ADA access and snown Total Project Valuation = \$ BedroomsNoEx: 0 BedroomsNoProp: 0 HeightofConstructionEx: 0 HeightofConstructionProp LivingAreaEx: 0.00 LivingAreaProp: 0.00	or Cabin by lift provider an vide platform for queue ar nelt. 55,855,000 .00	d to be reviewed by
	SignLength: 0.00 SignWidth: 0.00 StoriesNoEx: 0		
	StoriesNoProp: 0		

On this day we have inspected your construction for **Foundation Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

TotalAreaEx: 0.00 TotalAreaProp: 0.00

Comments: Vault lid rebar is per detail 2/S1.04 Rebar clearances and spacing is good for rebar





mat centered in slab OK to pour

Corrections:

Sincerely,

Don Marchbanks Inspector dmarchbanks@co.routt.co.us