

**NORTHWEST COLORADO CONSULTANTS, INC.**  
**FIELD REPORT**

<b>Project:</b> SBGBTR	<b>Project No.:</b> 21-12047	<b>Date:</b> 6/15/21
<b>Location:</b> SBS, CO	<b>Report No.:</b> 1-SP	<b>Time:</b> 1.5
<b>Client:</b> Steamboat Ski Corp.		<b>Mileage:</b> 12
		<b>Engr. /Tech:</b> JS

**Work Performed:**

As requested, we visited the project site on today's date to provide observations of the reinforcing steel placed for both the elevator/boiler room footing and the vault footing being constructed for the Steamboat Gondola relocation.

**Remarks:**

Based on our visual observations, the reinforcing steel noted above appeared to have been placed in general accordance with the structural drawings, sheet No.'s S1.01 and S1.04 by Anthem Structural Engineers, dated 4/20/21 and 6/7/21.

It should be noted that today's observations are made with respect to the rebar placement only and do not constitute a complete special inspection of the structure. Elements such as layout, size, elevations, or other architectural aspects are not considered in our observations.

**Verbal Discussions:**

Jose Gutierrez of Sierra Concrete Company was notified of today's observations.