



# INSPECTION REPORT

**Report Issued:** Nov 02, 2022

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** SPREL221498

**Issuance Date:** Oct 10, 2022

**Property Address:**

**Applicant:** STEAMBOAT SKI & RESORT CORP

**Contractor:**

**To construct:** wire Bashor Block house and replace electrical disconnect and wires

On this day we have inspected your construction for **Electrical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Underground for feeder to block house from service approved

**Corrections:**

Sincerely,

Tom Cook  
Electrical Plan Reviewer/Inspector  
tcook@co.routt.co.us