



INSPECTION REPORT

Report Issued:	Nov 03, 2022	Inspection Result	PARTIAL PASS
-			
Permit Number:	SPRPL220733		
Issuance Date:	Jun 06, 2022		
Property Address:			
Applicant:	Mechanical & Piping Inc		
Contractor:	Mechanical & Piping Inc 64	40 E. 50th Ave Comme	rce City, CO 80022 (303)
	710-2869		
To construct:	New Restaurant and Rest room, Wild Blue Gondola Mid Mountain.		

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Wild Blue Maintenance building roof drains and vents completed and passed hydrostatic test. Waterline to hose bibb installed and passed 100psi test. All waterlines, waste lines and roof drains completed. Will in spect Mechanical room when ready. Approved

Corrections:

Sincerely,

Ron Norton Inspector rnorton@co.routt.co.us