



# INSPECTION REPORT

**Report Issued:** Nov 17, 2022

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** SPRPL220733

**Issuance Date:** Jun 06, 2022

**Property Address:**

**Applicant:** Mechanical & Piping Inc

**Contractor:** Mechanical & Piping Inc 6440 E. 50th Ave Commerce City, CO 80022 (303) 710-2869

**To construct:** New Restaurant and Rest room, Wild Blue Gondola Mid Mountain.

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Gas line in Maintenance building installed from meter location to 6 heater locations. Gas line is sized at plans and properly supported. Gas line test is good at 29psi.  
Approved

**Corrections:**

Sincerely,

Ron Norton  
Inspector  
rnorton@co.routt.co.us