



INSPECTION REPORT

Report Issued: Dec 21, 2022

Inspection Result: **PARTIAL PASS**

Permit Number: SPRMH221626

Issuance Date: Nov 02, 2022

Property Address: 1901 CURVE PLZ;

Applicant: Air Comfort, Inc.

Contractor: Deneuve Design, Inc dba Deneuve Consrt. Serv 2344 Spruce Strt Ste B
Boulder, Co 80302

To construct: Mechanical HVAC

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: See correction and fix, all other ducts in units are installed, supported and sealed correctly.

Corrections:

- 1 1. Finish terminations and sealing joints in units 211-215
2. Seal one joint in unit 205, 207, 208, 209 and make sure all ducts are off sprinkler lines.
3. Dryer in 214 needs to be rerouted to not go into another unit.

Sincerely,

Silas Ebbert
Inspector
sebbert@co.routt.co.us