



# INSPECTION REPORT

**Report Issued:** Jan 19, 2023

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** SPRMH221626

**Issuance Date:** Nov 02, 2022

**Property Address:** 1901 CURVE PLZ;

**Applicant:** Air Comfort, Inc.

**Contractor:** Deneuve Design, Inc dba Deneuve Consrt. Serv 2344 Spruce Strt Ste B  
Boulder, Co 80302

**To construct:** Mechanical HVAC

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Entire fourth floor units have bathroom exhaust fans with dampers installed and run to outside and dryer vents properly installed to outside. All duct properly sealed and supported. Partial approved.

**Corrections:**

Sincerely,

Ron Norton  
Inspector  
rnorton@co.routt.co.us