



# INSPECTION REPORT

**Report Issued:** Jan 25, 2023

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** TB-21-834

**Issuance Date:** Oct 06, 2021

**Property Address:** 1857 RIVER QUEEN LN;

**Applicant:** Brstina LLC

**Contractor:** Brstina LLC P.O. BOX 883321 STEAMBOAT SPGS, CO 80488 (970) 846-4030

**To construct:** Work Description: Duplex Unit B

See Unit A, B-21-755 for valuation and fees

On this day we have inspected your construction for **Framing Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Partial: Interior side of separation has 5/8 drywall properly installed and fastened. Complete framing and install opposite side drywall for next inspection. Partial approved

**Corrections:**

Sincerely,

Ron Norton  
Inspector  
rnorton@co.routt.co.us