



# INSPECTION REPORT

**Report Issued:** Mar 01, 2023

**Inspection Result:** PASSED

**Permit Number:** SPRPL220628

**Issuance Date:** May 22, 2022

**Property Address:** 345 LINCOLN AVE, UNIT:205;

**Applicant:** Isidro Quezada

**Contractor:** IQ PLUMBING & HEATING 895 RANNEY ST CRAIG, CO 81625 (970) 629-5125

**To construct:** Install new drains and water lines to commercial unit. It will consist of 3 bathrooms a kitchen and a mechanical/laundry room.

On this day we have inspected your construction for **Plumbing Final Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** All fixtures installed, sealed and operational. Final approved

**Corrections:**

Sincerely,

Ron Norton  
Inspector  
rnorton@co.routt.co.us