



## **INSPECTION REPORT**

Report Issued: Apr 03, 2023 Inspection Result: PASSED

Permit Number: SPRPL221086 Issuance Date: Aug 03, 2022

Property Address: 1859 RIVER QUEEN LN;

**Applicant:** rogelio A Castro

**Contractor:** unlimited plumbing solutions 1736 cimarron st Aurora, CO 80011

**To construct:** plumbing a new duplex

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** DWV and waterlines run to locations on Approved Plans. All pipes are properly supported and protected. DWV test good at 6psi and waterlines at 90psi. Approved

## **Corrections:**

Sincerely,

Ron Norton Inspector rnorton@co.routt.co.us