



INSPECTION REPORT

Report Issued: Apr 05, 2023

Inspection Result: **PARTIAL PASS**

Permit Number: SPRMU220151

Issuance Date: May 05, 2022

Property Address: 1901 CURVE PLZ;

Applicant: May Riegler Properties, LLC (Gaby & Kevin Riegler)

Contractor: Deneuve Design, Inc dba Deneuve Consrt. Serv 2344 Spruce Strt Ste B
Boulder, Co 80302 Deneuve Design, Inc 2344 Spruce Strt Ste B Boulder, CO
80302 Eric Rehnberg 2344 Spruce St, Suit B Boulder, CO 80302 (303) 359-
0276

To construct: New 5-story, 73 unit, wood-framed residential apartment building.

On this day we have inspected your construction for **Framing Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Fire collar in unit 111 installed and fire caulked correctly.

Corrections:

Sincerely,

Silas Ebbert
Inspector
sebbert@co.routt.co.us