



INSPECTION REPORT

Report Issued:	Apr 13, 2023	nspection Result:	PARTIAL PASS
Permit Number: Issuance Date:			
Property Address:	1859 RIVER QUEEN LN;		
••	Brstina LLC		
	Brstina LLC P.O. BOX 883321		80488 (970) 846-4030
To construct:	Construct new duplex and de	tached garage	

Unit A: B-21-755 Unit B: B-21-834 Detached Garage: B-21-835

On this day we have inspected your construction for **Framing Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: inspected the squash blocks added on basement level under roof rafters that missed floor joists, also concrete patch is done in the basement.

Corrections:

Sincerely,

Todd Carr





Building Official tcarr@co.routt.co.us