



# INSPECTION REPORT

**Report Issued:** Apr 18, 2023

**Inspection Result:** **FAILED**

**Permit Number:** TB-21-834

**Issuance Date:** Oct 06, 2021

**Property Address:** 1857 RIVER QUEEN LN;

**Applicant:** Brstina LLC

**Contractor:** Brstina LLC P.O. BOX 883321 STEAMBOAT SPGS, CO 80488 (970) 846-4030

**To construct:** Work Description: Duplex Unit B

See Unit A, B-21-755 for valuation and fees

On this day we have inspected your construction for **Rough Site Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** The trash needs to be picked up throughout site and from snow storage piles on the street by end of next week or stop work order will be issued.

**Corrections:**

- 1 Clean up all trash in front of property and in surrounding snow storage piles. Especially micro bits of insulation board.

Sincerely,

Scott Slamal  
Stormwater Inspector  
sslamal@steamboatsprings.net