



# INSPECTION REPORT

**Report Issued:** May 11, 2023

**Inspection Result:** PASSED

**Permit Number:** SPRRN230332

**Issuance Date:** Apr 20, 2023

**Property Address:** 1865 SKI TIME SQUARE DR;

**Applicant:** Calcon Constructors, Inc

**Contractor:** Calcon Constructors, Inc 2270 W. BATES AVE. ENGLEWOOD, CO 80110 (720) 930-7150

**To construct:** Remodel existing office space. Scope includes removal and relocation of walls and doors to create additional storage space and open workspaces. Scope additionally includes relocation of sprinkler heads, electrical outlets and light switches.

On this day we have inspected your construction for **Framing Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Closed in three walls for additional space, steel studs, non load bearing.

**Corrections:**

Sincerely,

Jeff Yeiser  
Inspector  
jyeiser@co.routt.co.us