

# INSPECTION REPORT

**Report Issued:** May 12, 2023

**Inspection Result:** **FAILED**

**Permit Number:** SPRSW220558

**Issuance Date:** Jun 01, 2022

**Property Address:** 2400 MT WERNER CIR;

**Applicant:** Duckels Construction Inc.

**Contractor:**

**To construct:** New electrical conduit yvea duct bank project

On this day we have inspected your construction for **45 Day Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Thank you!

**Corrections:**

- 1 Maintain and/or remove damaged rock socks along Mt Werner cir.

Sincerely,

Scott Slamal  
Stormwater Inspector  
sslamal@steamboatsprings.net