



## **INSPECTION REPORT**

Inspection Result:	PASSED
	Inspection Result:

Permit Number: SPRRN230707 Issuance Date: Jul 10, 2023

**Property Address:** 2305 MT WERNER CIR;

**Applicant:** Calcon Constructors, Inc

Contractor: Calcon Constructors, Inc 2270 W. BATES AVE. ENGLEWOOD, CO 80110 (720)

930-7150

**To construct:** Remodel existing retail space to create two separate retail spaces from what

was previously one retail space. Scope of Work for Mechanical and Electrical is

limited to 'Base Bid' drawing details only.

On this day we have inspected your construction for **Drywall Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** New steel stud framed walls have 5/8 type x drywall installed and properly fastened. Approved

## **Corrections:**

Sincerely,

Ron Norton Inspector rnorton@co.routt.co.us