



INSPECTION REPORT

Report Issued: Aug 07, 2023

Inspection Result: PARTIAL PASS

Permit Number: SPREL230771

Issuance Date: Jun 22, 2023

Property Address: 821 DOUGHERTY RD;

Applicant: WESTERN ELECTRICAL SERVICE LLC

Contractor: WESTERN ELECTRICAL SERVICE LLC 1815 Central Park Dr, Suite 110 , Box 97
Steamboat Springs, CO 80487 (970) 846-5538

To construct: New mezzanine That we are doing the electrical for

On this day we have inspected your construction for **Electrical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Rough electric for 1st and 2nd floor of build-out on East end of church approved.
Rough electric on South Wall near curtain approved

Corrections:

Sincerely,

Tom Cook
Electrical Plan Reviewer/Inspector
tcook@co.routt.co.us