



INSPECTION REPORT

| Report Issued: | Sep 15, 2023 | Inspection Resul | t: | PASSED | |
|-------------------|---------------------------|---|-----|--------------------|--|
| | | | ••• | | |
| - | | | | | |
| Permit Number: | SPREL2308/1 | | | | |
| Issuance Date: | Jul 17, 2023 | | | | |
| Property Address: | 2305 MT WERNER CIR; | | | | |
| Applicant: | CENTRAL ELECTRIC, LLC | | | | |
| Contractor: | CENTRAL ELECTRIC, LLC 26 | 559 Jacob Cir #4 STEAN | ЛВС | AT SPGS,, CO 80487 | |
| | (970) 846-8379 | | | | |
| To construct: | Gondi Square Retail Cente | li Square Retail Center Remodel - Replace wiring, lighting and branch | | | |
| | circuits. | | | | |

On this day we have inspected your construction for **Electrical Final Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Final electrical approved

Corrections:

Sincerely,

Tom Cook Electrical Plan Reviewer/Inspector tcook@co.routt.co.us