



# INSPECTION REPORT

**Report Issued:** Oct 06, 2023

**Inspection Result:** **FAILED**

**Permit Number:** SPRMH230371

**Issuance Date:** Apr 13, 2023

**Property Address:** 1857 RIVER QUEEN LN;

**Applicant:** MOUNTAIN HIGH MECHANICAL

**Contractor:** Brstina LLC P.O. BOX 883321 STEAMBOAT SPGS, CO 80488 (970) 846-4030

**To construct:** Ventilation and air to water heat pump system.

On this day we have inspected your construction for **Mechanical Final Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** All items completed minus in floor heat system, once the system is running call back for a final. All bath exhaust and dryer exhaust are completed.

**Corrections:**

Sincerely,

Todd Carr  
Building Official  
tcarr@co.routt.co.us