



INSPECTION REPORT

Report Issued:	Oct 12, 2023	Inspection Result:	PASSED
•	•	iiispeetioii itesait.	IASSED

Permit Number: SPRRF231020 Issuance Date: Aug 29, 2023

Property Address: 2300 MT WERNER CIR;

Applicant: Misha Lawing

Contractor: Grand County Roofing and Sheet Metal P O Box 29 Granby, Co 80446 (970)

887-0104

To construct: Replacing a total of 40 SQ of Asphalt shingle (4 different sections) with new

Asphalt shingle and 100% ice and water shield underneath.

On this day we have inspected your construction for **Roofing Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Roof repair, SB Grand, decking replaced with FR 3/4" ply, IWS and shingles/flashings installed.

Corrections:

Sincerely,

Jeff Yeiser Inspector jyeiser@co.routt.co.us