



INSPECTION REPORT

Report Issued: Oct 13, 2023

Inspection Result: PASSED

Permit Number: SPRMH230363

Issuance Date: Apr 12, 2023

Property Address: 1859 RIVER QUEEN LN;

Applicant: MOUNTAIN HIGH MECHANICAL

Contractor: Brstina LLC P.O. BOX 883321 STEAMBOAT SPGS, CO 80488 (970) 846-4030

To construct: Ventilation and air to water heat pump system.

On this day we have inspected your construction for **Mechanical Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: no rough needed, all finals

Corrections:

Sincerely,

Todd Carr
Building Official
tcarr@co.routt.co.us