



# INSPECTION REPORT

**Report Issued:** Oct 13, 2023

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** SPRMH230363

**Issuance Date:** Apr 12, 2023

**Property Address:** 1859 RIVER QUEEN LN;

**Applicant:** MOUNTAIN HIGH MECHANICAL

**Contractor:** Brstina LLC P.O. BOX 883321 STEAMBOAT SPGS, CO 80488 (970) 846-4030

**To construct:** Ventilation and air to water heat pump system.

On this day we have inspected your construction for **Mechanical Final Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** All work completed, minus heat pumps, call back once heat pumps are operational including AC units.

**Corrections:**

- 1 complete heat pumps, call back once heat pumps are operational including AC units.

Sincerely,

Todd Carr  
Building Official  
tcarr@co.routt.co.us