



INSPECTION REPORT

Report Issued: Oct 25, 2023

Inspection Result: **FAILED**

Permit Number: SPRMH230363

Issuance Date: Apr 12, 2023

Property Address: 1859 RIVER QUEEN LN;

Applicant: MOUNTAIN HIGH MECHANICAL

Contractor: Brstina LLC P.O. BOX 883321 STEAMBOAT SPGS, CO 80488 (970) 846-4030

To construct: Ventilation and air to water heat pump system, and roughed in AC condensing lines but no ac units installed will require a future permit.

On this day we have inspected your construction for **Mechanical Final Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: All work completed, minus heat pumps, call back once heat pumps are operational

Corrections:

- 1 complete heat pumps, call back once heat pumps are operationa

Sincerely,

Todd Carr
Building Official
tcarr@co.routt.co.us