



INSPECTION REPORT

Report Issued:	Oct 27, 2023	Inspection Result:	PARTIAL PASS
----------------	--------------	--------------------	--------------

Permit Number: SPRPL231578 Issuance Date: Oct 26, 2023

Property Address: 1851 RIVER QUEEN LN;

Applicant: Isidro Quezada

Contractor: IQ PLUMBING & HEATING 895 RANNEY ST CRAIG, CO 81625 (970) 629-5125

To construct: Waste, vent, and water piping for new home at 1851 River Queen Ln.

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: In slab drains, complete and holding 5 psi

Corrections:

Sincerely,

Jeff Yeiser Inspector jyeiser@co.routt.co.us