



INSPECTION REPORT

Report Issued:	Nov 29, 2023	Inspection Result:	ΡΔςςέρ
•		inspection result.	I ASSED
Permit Number:	SPRMH231292		
Issuance Date:	Sep 12, 2023		
Property Address:	2305 MT WERNER CIR;		
Applicant:	Stephen Patterson		
Contractor:	TOLIN MECHANICAL SYSTE	MS CO. 12005 E. 45TH AV	E. DENVER, CO 80239-
	3111 (303) 859-0261		
To construct:	Replace the exhaust hood	fan at Rendezvous Station	

On this day we have inspected your construction for **Mechanical Final Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Rendezvous main floor hoods have a new power vent installed, sealed, complete and operational

Corrections:

Sincerely,

Jeff Yeiser Inspector jyeiser@co.routt.co.us