



INSPECTION REPORT

Report Issued: Dec 15, 2023

Inspection Result: PASSED

Permit Number: SPRRN231727

Issuance Date: Dec 14, 2023

Property Address: 2700 VILLAGE DR, UNIT:304;

Applicant: KRUSE BUILDERS, LLC

Contractor: KRUSE BUILDERS, LLC 996 Captain Jack Drive Steamboat Springs, CO 80487
(970) 629-5427 Ext: Jake

To construct: UNIT F-304

Patch Drywall after replacing fixtures

Slight moves in two non-load-bearing walls

Add Washer/Dryer hookups (none previously)

Please see work description in Architectural

On this day we have inspected your construction for **Framing Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: 2 non bearing walls reframed to plans and work description. Approved

Corrections:

Sincerely,

Ron Norton
Inspector
rnorton@co.routt.co.us