

Inspector



INSPECTION REPORT

Report Issued:	Jan 10, 2024	Inspection Result:	PARTIAL PASS
Permit Number:	SPRRN231351		
Issuance Date:	Dec 04, 2023		
Property Address:	3367 APRES SKI WAY;		
Applicant:	ALDRICH BUILT		
Contractor:	ALDRICH BUILT PO BOX 88 2475	32943 STEAMBOAT SPRIN	IGS, CO 80488 (970) 819-
To construct: On this day we have in:	inside of the home with the existing and are being repubasement apartment. The		or doors. These doors are be updating the existing ill be completely redone. hting plan and drywall
following result of the address below.	inspection. If there are a	ny questions, please call	the inspector at the
Comments: First layer mech room.	of drywall has been insta	lled, meets fastener scho	edule. All rooms except
Corrections:			
Sincerely,			
Jeff Yeiser			





jyeiser@co.routt.co.us