



INSPECTION REPORT

Report Issued: Mar 25, 2024

Inspection Result: **FAILED**

Permit Number: SPRRN240169

Issuance Date: Mar 22, 2024

Property Address: 1865 SKI TIME SQUARE DR, UNIT:DS-2C;

Applicant: William Banks

Contractor: HLCC CONSTRUCTION CO. 2667 COPPER RDG CIR #2 STEAMBOAT SPGS, CO 80487 (970) 879-6831

To construct: removal of none weight bearing wall. Extend bar. Add a beer cooler. add three plywood booths. This work was done in CY2022 without a permit being applied for, all work is completed at this point.

On this day we have inspected your construction for **Building Final Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Need to remove illegal trap in vent pipe under stairs and run water heater condensate line to mop sink. Need to run walk in cooler condensate line to mop sink. Schedule inspection when completed.

Corrections:

Sincerely,

Ron Norton
Inspector
rnorton@co.routt.co.us