



# INSPECTION REPORT

**Report Issued:** Apr 19, 2024

**Inspection Result:** PASSED

**Permit Number:** SPRNR230776

**Issuance Date:** Jul 03, 2023

**Property Address:** 1716 COPPER RIDGE SPUR, UNIT:C2;

**Applicant:** Richey Construction

**Contractor:** Richey Construction PO Box 775272 Steamboat Springs, CO 80477 (970) 846-1168

**To construct:** New Duplex style Live Work Unit 2

See SPRNR230582 for Unit 1

On this day we have inspected your construction for **Insulation Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Walls have 2 inches of closed cell foam with R13 batts over top. Floors have R38 batts installed and roof has 18 inches of blown fiberglass in place. Required R Values achieved.

**Corrections:**

Sincerely,

Ron Norton  
Inspector  
rnorton@co.routt.co.us