



# INSPECTION REPORT

**Report Issued:** Nov 01, 2024

**Inspection Result:** PASSED

**Permit Number:** SPRPL241703

**Issuance Date:** Oct 25, 2024

**Property Address:** 2305 APRES SKI WAY, UNIT:230;

**Applicant:** MASTERWORKS MECHANICAL INC.

**Contractor:** MASTERWORKS MECHANICAL INC. 461 YAMPA CRAIG, CO 81625 (970) 824-4840

**To construct:** Installation of 2 shower pans

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** Upstairs shower pan installed, sealed and held water for test duration.

**Corrections:**

Sincerely,

Ron Norton  
Inspector  
rnorton@co.routt.co.us