



INSPECTION REPORT

Report Issued: Nov 22, 2024

Inspection Result: **PARTIAL PASS**

Permit Number: SPRPO241044

Issuance Date: Nov 04, 2024

Property Address: 3300 S LINCOLN AVE;

Applicant: Maurer Construction LLC

Contractor: Maurer Construction LLC 2621 Connery Way Missoula, MT 59808 (406) 542-6565

To construct: Pool for new hotel

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Pool rough, one gauge, holding 35 psi for three weeks

Corrections:

Sincerely,

Jeff Yeiser
Inspector
jyeiser@co.routt.co.us