



INSPECTION REPORT

Report Issued: Jan 13, 2025

Inspection Result: PASSED

Permit Number: SPRPL241910

Issuance Date: Dec 24, 2024

Property Address: 1920 BRIDGE LN, UNIT:14;

Applicant: Karl Holt

Contractor: CROSS MOUNTAIN PLMB & HEAT P.O. BOX 771905 STEAMBOAT SPGS,, CO
80477 (970) 819-4276

To construct: Adding washer waste box and water line box on 2nd floor. Altering/correcting washer waste box and water lines on 1st floor.

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: New washer box properly installed on lower level. Waterlines are live and DWV passed flow test. Approved. Plumbing in kitchen completed. Will need to install hammer arrester on dishwasher supply.

Corrections:

Sincerely,

Ron Norton
Inspector
rnorton@co.routt.co.us