



INSPECTION REPORT

Report Issued: Jan 16, 2025

Inspection Result: PASSED

Permit Number: SPRPL241910

Issuance Date: Dec 24, 2024

Property Address: 1920 BRIDGE LN, UNIT:14;

Applicant: Karl Holt

Contractor: CROSS MOUNTAIN PLMB & HEAT P.O. BOX 771905 STEAMBOAT SPGS,, CO
80477 (970) 819-4276

To construct: Adding washer waste box and water line box on 2nd floor. Altering/correcting washer waste box and water lines on 1st floor.

On this day we have inspected your construction for **Plumbing Final Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

Comments: Hammer arrestor installed under kitchen sink, all fixtures are operable, caulked and leak free. Final approved.

Corrections:

Sincerely,

Silas Ebbert
Inspector
sebbert@co.routt.co.us