



# INSPECTION REPORT

**Report Issued:** Jan 21, 2025

**Inspection Result:** PARTIAL PASS

**Permit Number:** SPRPL240545

**Issuance Date:** May 17, 2024

**Property Address:** 322 RIVERVIEW WAY;

**Applicant:** Bellyache Mechanical

**Contractor:** Bellyache Mechanical PO BOX 82 Wolcott , CO 81655 (970) 470-3341

**To construct:** Building B New Plumbing install

On this day we have inspected your construction for **Plumbing Rough-in Inspection** and we find the following result of the inspection. If there are any questions, please call the inspector at the address below.

**Comments:** DWV installed to locations on approved plans in units. 214, 219, 314, 319, 413, 414, and 415. DWV pipe in these unit is properly supported and protected and all passed test of 5.5psi. Partial approved

**Corrections:**

Sincerely,

Ron Norton  
Inspector  
rnorton@co.routt.co.us